



INCRA Aluminum MagnaLOCK Plate Compatibility

Rev 01/2012

| | | MLP-Undrilled | MLP1613-AL | MLP1619-AL | MLP3612C-AL | MLP621625-AL | MLP690890-AL | MLP7518-AL | MLPFT2000-AL | MLPFT3000-AL | MLPM12V-AL |
|---------------------|--------------------------|---------------|------------|------------|-------------|--------------|--------------|------------|--------------|--------------|------------|
| Bosch | 1617, 1618 | | | | | | *2 | | | | |
| | MRC23 | | | | | | *2 | | | | |
| | 1613 | | ✓ | | | | | | | | |
| | 1619 | | | ✓ | | | | | | | |
| | 1611 | | | | | ✓ | | | | | |
| DeWalt | DW610 | ✓ | | | | | | | | | |
| | DW618 | | | | | | ✓ | | | | |
| | DW621, DW625 | | | | | ✓ | | | | | |
| Fein | RT-1800 | | | | | ✓ | | | | | |
| Freud | FT-1700 | ✓ | | | | | | | | | |
| | FT-2000, FT2200 | | | | | | | | ✓ | | |
| | FT-3000 | | | | | | | | | ✓ | |
| Hitachi | M12-V (older 3hp plunge) | | | | | | | | | | ✓ |
| | M12-V2 (new 3hp plunge) | ✓ | | | | | | | | | |
| | M12-VE (new 3hp plunge) | | | | | | | | | | ✓ |
| | M12-VC (2hp fixed/kit) | ✓ | | | | | | | | | |
| Makita | 3612-C | | | | ✓ | | | | | | |
| | RP-2301 | ✓ | | | | | | | | | |
| | RF-1101, RF1100 | | | | | | ✓ | | | | |
| Milwaukee | 5615, 5616 | | | | | | *2 | | | | |
| | 5625 | | | | | | | *2 | | | |
| Porter-Cable | 690-699 series | | | | | | ✓ | | | | |
| | 890-899 series | | | | | | ✓ | | | | |
| | 7529, 8529 | | | | | | ✓ | | | | |
| | 7518, 7519 | | | | | | | ✓ | | | |
| | 7538, 7539 | | | | | | | ✓ | | | |
| Ridgid | R2930 | | | | | | *2 | | | | |
| Triton | TRC-001 | | | | | | | *1, 2 | | | |
| | TRA-001 | | | | | | | *1, 2 | | | |
| | MOF-001KC | | | | | | | *1, 2 | | | |
| | JOF-001 | ✓ | | | | | | | | | |

Notes:

*1 - Requires mounting bolts (not included)

*2 - Access for above-the-table height adjustment may need to be drilled.